## United States Environmental Protection Agency Criminal Investigation Division Investigative Activity Report

## **Case Number**

0500-0614

**Case Title:** 

Village of Crestwood, IL

**Reporting Office:** 

Chicago, IL, Area Office

Subject of Report:

Interview of (6), (6), (7)(C) on September 9, 2010

Activity Date:

September 9, 2010

Reporting Official and Date:

(b) (6), (b) (7)(C) , SA 28-SEP-2010, Signed by: (b) (6), (b) (7)(C) , SA Approving Official and Date:

(b) (6), (b) (7)(C) , SAC 29-SEP-2010, Approved by: (b) (6), (b) (7)(C) , ASAC

## SYNOPSIS

09/09/2010 - On September 9, 2010, (b) (6), (b) (7)(c) was interviewed. (c) (6) (6) (7)(c) was interviewed. (d) (6) (6) (7)(c) (6) (7)(c) (7)(

## **DETAILS**

On September 9, 2010, (b) (7) (c) ), was interviewed by this reporting agent (RA), Special Agent (b) (6), (b) (7) (c) and Special (b) (6), (b) (7) (c) , of the U.S. Environmental Protection Agency Criminal Investigation. This interview was conducted at the offices of Layne Western, 721 W. Illinois Avenue, Aurora, IL, where (b) (6), (c) (d) (d) is employed.

Upon meeting (b) (6). (b) agents displayed EPA-CID credentials to them. Agents advised (b) (6). (b) that they wished to speak to (c) regarding (c) employment at Layne Western, specifically regarding issues relating to (c) previous dealings with the Village of Crestwood, IL. (c) (6). (c) agreed to speak with agents.

In summary and not verbatim unless otherwise noted, (b) (6), (b) provided the following information:

is currently employed as a Senior Project Manager for Layne. has been with the company since 1982. (b) (6), (b) was previously responsible for handling sales calls for the Village of Crestwood, IL.

After reviewing records, (b) (6), (b) indicated that the last time that was in Crestwood for work was in 1995. (c) (6), (b) indicated that the last time that was in Crestwood for work was in 1995.

The only type of work that was performed on the well by Layne was relating to the pumping equipment, in an around the head of the well. No work on the distribution system, like the piping, would have ever been performed by Layne. That is not the type of work that they complete.

Without further review of the Layne records relating to Crestwood. (b) (6), (b) could provide no further details regarding work in Crestwood.

This document contains neither recommendations nor conclusions of the EPA.

It is the property of the EPA and is loaned to your agency;
it and its contents are not to be distributed outside your agency.

OCEFT Form 3-01 (01/10) Page 1 of 1